

**Hensley & Komatsu GET Bucket Teeth x 9 to suit Various**



<b>Make</b>	Hensley, Komatsu		<b>Model</b>	GET Bucket Teeth x 9 to suit Various	
<b>Year</b>		<b>Hours</b>		As at	
<b>Mileage</b>				As at	
<b>Serial/VIN</b>				<b>Engine Serial</b>	
<b>Details</b>	<p>Hensley &amp; Komatsu GET Bucket Teeth x 9 to suit Various. Asset ItemID_4690. Komatsu Bucket Teeth x 4 with Part unknown. Komatsu Bucket Tooth x 1 to suit PC300 with Part unknown.</p> <p>Hensley Rocket Penetrator Bucket Teeth x 2 to suit PC800 Part XS85RP2. As a guide only, the estimated replacement costs is \$1350, and we have collected Data from Parts search at: <a href="https://my.komatsu.com.au/shop/teeth_5637144816/5637630156_hensley-rock-penetrator-tooth_xs85rp2">https://my.komatsu.com.au/shop/teeth_5637144816/5637630156_hensley-rock-penetrator-tooth_xs85rp2</a>. Description: Teeth .</p>				

Part no XS85RP2.  
Listed Price: 677 per unit.  
Brand: Hensley GET.  
In Stock.  
Hensley KMAX Tooth Sharp Ribbed x 2 Part K25SYL  
As a guide only, the estimated replacement costs is \$350, and we have collected Data from Parts search at:  
[https://my.komatsu.com.au/shop/allmakes\\_5637144748/5637578768\\_kmax-tooth--sharp-ribbed\\_k25syl](https://my.komatsu.com.au/shop/allmakes_5637144748/5637578768_kmax-tooth--sharp-ribbed_k25syl).  
Description: Teeth.  
Part no K25SYL.  
Listed Price: 172 per unit.  
Brand: Hensley GET.

<b>Asking price</b>		Under review - call for pricing	ex site	Australia, Western Australia, Welshpool
---------------------	--	---------------------------------	---------	---

**For further details, to make an offer or book an inspection, contact  
Global Equipment Solutions on Office: 08 9201 1142**