

**Komatsu Grouser Plates x 2 Part 207-32-61320 ItemID\_4325**



<b>Make</b>	Komatsu		<b>Model</b>	Grouser Plates x 2 Part 207-32-61320	
<b>Year</b>		<b>Hours</b>		As at	
<b>Mileage</b>				As at	
<b>Serial/VIN</b>				<b>Engine Serial</b>	
<b>Details</b>	<p>Komatsu Grouser Plates x 2 Part 207-32-61320.          Asset ItemID_4325.          As a guide only, the estimated replacement costs is \$113, and we have collected Data from Parts search at: <a href="https://my.komatsu.com.au/search-results?q=207-32-61320">https://my.komatsu.com.au/search-results?q=207-32-61320</a>.          Description: Track Shoe 800Mm T/B.          Part no 207-32-61320.          Listed Price:113 per unit.          Brand: Komatsu Limited.          Model Compatibility: HB335LC-1, HB365LC-3, PC250-6, PC270-7, PC270-8, PC270LC-8, PC290LC-11, PC300-6, PC300-7, PC300-7E0, PC300-8, PC300-8M0, PC300LC-6, PC300LC-7, PC300LC-7E0, PC300LC-8, PC300LC-8M0, PC300SC-6, PC350LC-6, PC350LC-7E0, PC350LC-</p>				



8, PC308USLC-3, PC350-7E0, PC350LC-7				
<b>Asking price</b>		Under review - call for pricing	ex site	Australia, Western Australia, Welshpool

**For further details, to make an offer or book an inspection, contact  
Global Equipment Solutions on Office: 08 9201 1142**