

Franna AT18 Damaged PTO range box



Make	Franna		Model	AT18 Damaged PTO range box	
Year		Hours	351	As at	11/09/2019
Mileage				km	As at
Serial/VIN	3288		Engine Serial	H07CTA 44098	
Details	<p>Franna AT18. Photos as at September 2019 showing out of service tag and log book entires. This crane has a damaged PTO range box that has been cracked and will require repair prior to go into operation but is running to drive on to buyers transport. We have no other maintenance history data on this unit and it is sold in "As Is" basis running to drive on to buyers transport. Available ex Century Mine Site Lawn Hill area via Gregory, North West Queensland, Australia.</p>				
Asking price	AUD	\$39,750 plus GST if applicable	ex site	Australia, Queensland, Lawn Hill	

For further details, to make an offer or book an inspection, contact

ADN Group Management Pty Ltd t/as Global Equipment Solutions
 Suite 7 / 401 Oxford Street Mount Hawthorn, Western Australia 6016
 PO Box 570, Floreat, 6014 Western Australia
 p: +61 (0) 8 9201 1142 | www.g-es.net | email: info@g-es.net
 ABN 28 593 584 022 | DL: MD23768



Global Equipment Solutions on Office: 08 9201 1142

ADN Group Management Pty Ltd t/as Global Equipment Solutions
Suite 7 / 401 Oxford Street Mount Hawthorn, Western Australia 6016
PO Box 570, Floreat, 6014 Western Australia
p: +61 (0) 8 9201 1142 | www.g-es.net | email: info@g-es.net
ABN 28 593 584 022 | DL: MD23768